



Initial look with cosmic

- Due to different cable length (~90 ft), there is a ~150 ns timing difference
- →Can be fixed by replacing cables or adding delay box
- Blue is a hodoscope output (H2L16 → changed to H2L4)



Connect the scope with Ethernet cable, so we can check the scope with VNC in the counting house





Monitoring with beam Integrated pulse during a few seconds of collisions

